

Huijue switch optical port failure



Overview

Problem: All optical ports cannot be connected, and the indicator lights are not on.

Solution: To solve this problem, you can follow these steps: Check if the fiber and optical modules are compatible. Single-mode/multimode fibers and single-mode/multimode optical modules cannot be. This document describes how to check the switch interface or port status and how to locate an interface physically down fault and restore the interface to the up state. Perform a. Based on typical issues encountered with optical modules in daily switch applications, this document summarizes basic troubleshooting steps for resolving common faults: 1. HUAWEI S Series Switch related case link: [more HUAWEI S Series Switch-Handle an Optical Interface's Failure to Go Up](#) video provides guidance on. A Huawei S12708 switch experienced excessive fan spinning due to a faulty optical module. This incident highlights the importance of proactive maintenance and monitoring.

Article Content

Typical Troubleshooting Cases of Optical Module

Check whether the optical module is a Huawei-certified one. If not, replace it with a Huawei-certified optical module. If the optical module is installed on a GE port, run the display interface ...

Optical Module Application: Common Problems & Troubleshooting ...

Based on typical issues encountered with optical modules in daily switch applications, this document summarizes basic troubleshooting steps for resolving common faults:

Solved Problem with a Huawei Switch

As soon as the port speed is changed, the name of the ports change from 100GE to 40GE. The QSFP28 cables, which was accepted in the 100GE modus, wasn't be recognized. I have ...

Huawei Switch Fan Issue Linked to Optical Module Failure

A Huawei S12708 switch experienced excessive fan spinning due to a faulty optical module. Replacing the module resolved the issue. This incident highlights the importance of ...

HUAWEI S Series Switch-Handle an Optical Interface's Failure ...

HUAWEI S Series Switch-Handle an Optical Interface's Failure to Go Up video provides guidance on how to handle an optical interface's failure to go Up. HUAWEI S Series Switch...

Troubleshooting S Series Switch Port and Interface Problems

When connecting two devices, check whether optical modules match optical interfaces, whether optical modules match fiber models, and whether optical modules and fibers are connected correctly.

Troubleshooting for Optical Modules on Huawei Switch

If the transmit power remains low, replace the optical module or install it in another optical port to check whether it is faulty. If the optical module is faulty, send it to Huawei for repair or ...

5 Most Common Failures Of Switches And Their Solutions

This kind of failure can firstly confirm that the protocol implementation has a standard interface, and secondly, accurately configure the parameters of the protocol interface to ensure the ...

Optical Link Failure Troubleshooting: Switch-to-Switch (SMF/MMF) ...

This article will elaborate on the core influencing factors, common causes, and targeted troubleshooting steps of optical link failures between switches, providing practical guidance for operation and ...

Optical Module Solutions for Huawei S5700/S5720 Series Switches

Problem: All optical ports cannot be connected, and the indicator lights are not on.

Solution: To solve this problem, you can follow these steps: Check if the fiber and optical modules ...

Contact Us

For more information, pricing, or custom solutions, please contact us:

Website: <https://sdesign.net.pl>

Email: sales@sdesign.net.pl

Phone: +48 694 237 815

Address: ul. Marszałkowska 10, 00-001 Warsaw, Poland

This document is for informational purposes only. Specifications subject to change without notice.

